

# KR203 Zebra thermal printer Windows Fix

March 25, 2022

This article describes how to solve if some printers do not react over USB after Windows updates.

## Issue / Question

How do I make the printers operative again after the latest Windows Security updates?


## Applicable To

Kiosk Printer Driver Version 1.3.510.109

## Resolution / Answer

Computer\HKEY\_LOCAL\_MACHINE\SYSTEM\CurrentControlSet\Control\Print\Printers\Zebra KR203

- Modify the **Attributes** registry value to 1.
- Restart the spooler service and restart the PC.



- By applying this fix you will disable bi-directional printing. This means you will no longer receive "out of paper messages" when the paper runs out. Restart the spooler service and restart the PC.
- You should engage your IT staff to implement this registry fix.